

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
HIROSHI NAKAHATA) : Examiner: Huan Tran
Appl. No.: 10/508,796) : Group Art Unit: 2861
Filed: September 21, 2004) : Confirmation No.: 3912
For: COLOR IMAGE FORMING APPARATUS) :
Patent No.: 7,173,646 B2) :
Issued: February 6, 2007) June 28, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/William M. Wannisky/

William M. Wannisky
Attorney for Patentee
Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

WMW:eyw

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,173,646 B2

DATED : February 6, 2007

INVENTOR(S) : HIROSHI NAKAHATA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 19, "cross sectional" should read --cross-sectional--.

Line 29, "puter etc." should read --puter, etc.,--.

Line 57, "(i.e.," should read --(i.e.,--.

Line 67, "f" should read --fθ--.

COLUMN 2:

Line 9, "image." should read --image may occur.--.

Line 25, "cleaner etc." should read --cleaner, etc.,--.

Line 54, "is" should read --is a--.

COLUMN 3:

Line 36, "drums etc." should read --drums, etc.,--.

Line 38, "(i.e.," should read --(i.e.,--.

Line 61, "cleaner 7" should read --cleaner 7,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,173,646 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,173,646 B2

DATED : February 6, 2007

INVENTOR(S) : HIROSHI NAKAHATA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 12, "(i.e." should read --(i.e.,--.

Line 37, "drums etc." should read --drums, etc.,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,173,646 B2

No. of add'l. copies
@ 30¢ per page

